CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date 20170120-E210133 E210133-20001221 2017-JANUARY-20

Issued to: ROTORK INSTRUMENTS ITALY SRL VIA PORTICO 17 24050 ORIO AL SERIO BG ITALY

This is to certify that representative samples of

SWITCHES, INDUSTRIAL CONTROL See addendum for models.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:	UL508, Industrial Control Equipment CSA C22.2 No. 14-13, Industrial Control Equipment
Additional Information:	See the UL Online Certifications Directory at <u>www.ul.com/database</u> for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.

Barnally

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date 20170120-E210133 E210133-20001221 2017-JANUARY-20

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Old nomenclature:

USL/CNL - Rotary Limit Switches, Models CA or CS; followed by an alpha numeric character; followed by S1, 01, S3, 03, 05, 06, 13, 14, 70, 71, 73, 2U, 2Z, 3U, 3Z, N1, N2, N3, 3M, 3P, 4M, TA, TB, TM, TX, DC or DE; followed by 0, 1, 2, 3 or 4; followed by 0, 1 or X; followed by an alphanumerical character; followed by E, F, N, H or 2; followed by an alphanumerical character.

New nomenclature:

USL/CNL - Rotary Limit Switches, Models SF, SS or SB; followed by 01, S1, 03, S3, 1F, 06, C1, C3, C4, C8, 2U, 2Z, 3U, 3Z, 3M, 3P, 4M, 4N, 4P, N1, N2, N3, 70, 71, 73, DC, DE, TA, TB, TX, T1, T2, TM, TN, T0, T#; followed by 0, 1, 2, 3 or 4; followed by two alpha numeric characters; followed by 1, 2, N or an alpha numeric character; followed by five alphanumerical characters; followed by 6, 7, 3 or 2; followed by three alphanumerical characters.

Barnally

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/