



Due to the paint thickness demands in ATEX and IECEx certification we need to slightly update our paint process for painting of a complete RC200 or RC88 actuator. Our painting specifications P4 (980597, 980596) and for C5 environment P5 (980598) needs to be updated to align with the demands in ATEX and IECEx certification.

We are updating our paint systems and will finalize tests to fulfil the demands as soon as possible. Orders in process will be analysed with our sales team and communicated to customers for best alternative solution.

We can offer our RCT actuator that is approved for C5 environment. For custom specific topcolour we can offer RCT with paint P2 (980599).

RCT in brochure PUB064-002-00-0919 Rotork: RCT200 and RCT88 sales flyer

Falun 2022-04-29

Sven Egerhag

Plant Manager Rotork Sweden AB





+46 (0)23 587 45